

D10 DAC Basic Set-up Tips

1. Select DAC menu
2. Select draw in “mode” parameter
3. With “cursor” parameter selected, use wheel to manoeuvre white bar over first peak (must be between 5% and 95% fsh)
4. Press and hold ok with cursor over peak response and “cursor” parameter still selected (small square appears)
5. Once all responses have been plotted select “mode” parameter and select “ON”
6. DAC curve will be calculated by D10